

SSMP-K-TFlex405 ASSEMBLY INSTRUCTION


1. Stripping Dimension

内导体 Inner conductor

外导体 Outer conductor

护套 Jacket

a. Stripping as pic. Kindly note that do not damage inner shield.




2. Assemble Dielectric and Soldering Center Contact

焊锡孔 tin-soldering hole

绝缘垫片 Dielectric

a. Pls add full and average tin when soldering, avoiding false soldering



3. Assemble label and heatshrink

4. Assemble connector

加锡焊接 tin-soldering

a. Assemble connector as pic.

b. Pls add full and average tin when soldering, avoiding false soldering

